



# VALIANT

Exterior 100% Acrylic  
High Build Coating  
Satin • 66301

## Product Description

**Valiant Exterior 100% High Build Acrylic Coating** is designed to provide flexibility, durability and weather resistance. Its high build formulation and 100% acrylic resins offer excellent dirt pick-up, mold and mildew resistance, as well as application in temperatures as low as 40° F \*\*. Ideal for use in residential, commercial, architectural and light industrial applications.

<p><b>Recommended Substrates</b></p> <ul style="list-style-type: none"> <li>Concrete, concrete block (CMU) and stucco</li> <li>Poured and precast concrete</li> <li>Synthetic EIFS &amp; synthetic masonry stucco</li> <li>Cementitious siding &amp; fiber cement siding</li> <li>Primed metals</li> <li>Primed woods</li> </ul> <p><b>Product Features</b></p> <ul style="list-style-type: none"> <li>Cold temperature application &gt;40° F **</li> <li>Excellent dirt pick-up resistance</li> <li>Excellent resistance to mildew and organic growth</li> <li>Highly breathable &amp; flexible film</li> <li>Outstanding hiding &amp; coverage properties</li> </ul> <p><b>Product Limitations</b></p> <p>This product is for use on properly prepared above grade vertical substrates. Do not apply to horizontal surfaces or areas that come in constant contact with moisture or standing water.</p> <p><b>Compliance</b></p> <p>This product is VOC compliant based on limits provided by EPA, MPI GPS-1 and OTC Phases 1 &amp; 2.</p>	<p><b>Cold Weather Painting **</b></p> <p>Only apply when product, air and substrate temperature are at least 40° F and 5° F above the dew point. For large expanses of metal siding and/or using most primers, the air, surface and material temperature must be 50° F and rising. Do not apply if air or substrate temperatures are expected to fall below 40° F within 48 hours. Do not apply if rain or snow is expected within 3 - 4 hours.</p> <p><b>Available bases   66301:</b> WB   MTB   NTB</p> <p><b>Application:</b> Brush, roller, airless or conventional spray</p> <p>Dry time @ 50% RH* @ <b>40-50° F</b> @ <b>&gt;50° F</b>          To touch 2 - 4 HRS 2 - 3 HRS          To recoat 24 - 48 HRS 4 HRS</p> <p><small>*dry times listed may vary according to the relative humidity, temperature, film build, color and air movement of the application environment</small></p> <p>Flash Point: NonFlammable &gt;200°F          Clean Up: Soap and water</p> <p><b>Performance Data</b></p> <table border="0"> <tr><td>Alkali Resistance</td><td>ASTM D1308</td><td>Passes</td></tr> <tr><td>Elongation</td><td>ASTM D2370</td><td>394%</td></tr> <tr><td>Dirt Pickup Resistance</td><td>Dc Rating</td><td>91.7</td></tr> <tr><td>Mildew &amp; Algae Resistance</td><td>ASTM D3273/74</td><td>Passes</td></tr> <tr><td>Tensile Strength (PSI)</td><td>ASTM D2370</td><td>282</td></tr> <tr><td>Water Vapor Permeance</td><td>ASTM D1653</td><td>19.0</td></tr> <tr><td>Wind-Driven Rain Test</td><td>ASTM D6904</td><td>Passes</td></tr> </table>	Alkali Resistance	ASTM D1308	Passes	Elongation	ASTM D2370	394%	Dirt Pickup Resistance	Dc Rating	91.7	Mildew & Algae Resistance	ASTM D3273/74	Passes	Tensile Strength (PSI)	ASTM D2370	282	Water Vapor Permeance	ASTM D1653	19.0	Wind-Driven Rain Test	ASTM D6904	Passes	<p><b>Product Data</b></p> <p>Product Type: <b>Waterborne / 100% Acrylic</b></p> <p>Gloss @60°: <b>66301</b> 10-20</p> <p>Wt Solids ±2%: 52%          Vol Solids ±2%: 40%</p> <p>Wet Film Mils: 4.0 - 16.0          Dry Film Mils: 3.2 - 6.4          Coverage / Gal * 100 - 200</p> <p>* coverage and wet and dry millage will vary by substrate type and porosity.          VOC gm p/L **: &lt;100          ** less exempt solvents and before the addition of colorant          Viscosity KU ±5: 115</p>
Alkali Resistance	ASTM D1308	Passes																					
Elongation	ASTM D2370	394%																					
Dirt Pickup Resistance	Dc Rating	91.7																					
Mildew & Algae Resistance	ASTM D3273/74	Passes																					
Tensile Strength (PSI)	ASTM D2370	282																					
Water Vapor Permeance	ASTM D1653	19.0																					
Wind-Driven Rain Test	ASTM D6904	Passes																					

## Surface Preparation

**WARNING!** If you scrape, sand, or remove old paint, you may release lead dust or fumes. LEAD IS TOXIC. EXPOSURE TO LEAD DUST OR FUMES CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a properly fitted NIOSH-approved respirator and prevent skin contact to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the USEPA National Lead Information Hotline at 1-800-424-LEAD or log on to [www.epa.gov/lead](http://www.epa.gov/lead).

**General Surface Preparation:** The performance of this product is dependent on the integrity and soundness of the substrate. All surfaces should be clean and free of any dirt, rust, grease, mill oils, mill scale, efflorescence, organic growth, mildew or other contaminants that might adversely affect the adhesion and performance of this product. Any failed or deteriorated caulk or patching compound should be removed and replaced. Unpainted surfaces should be primed in accordance with manufacturer's recommendations. Glossy substrates should be deglossed prior to painting.

**Drywall & Plaster:** Nails or screws should be countersunk, and they along with any indentations should be mudded flush with the surface, sanded smooth and cleaned to remove any dust, then primed or sealed prior to painting the substrate. Plaster, hardcoat, skim coat or other alkaline surfaces should be allowed to cure for at least 30 days prior or prime with an alkali resistant primer.

**New Concrete, Stucco and Masonry Surfaces:** Valiant can be applied to new concrete after curing a minimum of seven (7) days and the pH of the substrate must be less than 13. For optimal performance, new concrete, stucco and block mortar joints should cure at least 30 days with a pH of 10 or less or prime with an alkali resistant primer. Fill block with appropriate blockfiller.

**Wood:** Unpainted wood or wood in poor condition should be sanded smooth, wiped clean and then primed. Any knots or resinous areas must be primed before painting. Countersink all nails, putty flush with surface, then prime with a quality stain blocking primer.

**Ferrous Metal:** The surface must be cleaned thoroughly to remove any dust, rust, and surface contaminants and then primed with a corrosion resistant primer.

**Application:** Stir product thoroughly in a spiral up and down motion before use and during application. Use a quality nylon or polyester brush, a 1/2" to 1-1/4" nap synthetic roller cover, or airless sprayer with a minimum pressure of 2000 PSI and a .021" tip. To assure color uniformity intermix multiple containers of same color and apply a small test area to verify color.

**Thinning:** Stir thoroughly and apply as it comes from the container, thinning is not necessary under normal conditions.

**Coverage & Dry Time:** Covers approximately 300 - 400 square feet per gallon, depending on the method of application and the porosity of the surface to be painted. Dries to touch at 50°F or greater in approximately 2 - 3 hours and may be recoated in 4 hours when humidity is low. Colder temperatures will take longer, see above. Do not apply when air, surface or product temperatures are below 40°F or above 100°F. Cleaning should not occur until 30 days after the initial application.

**Clean Up:** Minor spills and splatters should be immediately cleaned with soap and water, as well as any painting tools and airless spray equipment. More serious spills should be contained and removed with inert absorbent material. Dispose of contaminated absorbent, container and unused contents in accordance with local, state and federal regulations.

**Safety - CAUTIONS: KEEP OUT OF REACH OF CHILDREN! DO NOT TAKE INTERNALLY! USE ONLY WITH ADEQUATE VENTILATION!** Avoid prolonged contact with skin, and breathing of dust, vapors or spray mists. Avoid contact with eyes and wear eye protection. If adequate ventilation is not possible, wear a NIOSH approved respirator to avoid inhalation of the fumes and wear clothing designed to prevent skin contact. Wash skin thoroughly after handling. Close container after each use and store in a secure, shaded and dry location. **First Aid:** Wash skin thoroughly with plenty of warm soap and water. In case of eye contact immediately flush with plenty of water for 15 minutes and get medical attention immediately. If you experience difficulty breathing leave area to obtain fresh air. If continued difficulty is experienced get medical attention immediately. If swallowed do not induce vomiting and get medical attention immediately.

## Storage and Disposal

Product should be kept from freezing temperatures & stored in a cool, dry location. Refer to your local city or county government for instructions on disposal options.

Spectrum Paints believes the technical data represented in this technical bulletin to be current and up to date. However, Spectrum Paints makes no warranties or guarantees either expressed or implied. Spectrum Paints claims no responsibility from damages incurred from use by either the purchaser or user of the product.

66301 2304

## Spectrum Paint Company

15247 E. Skelly Drive | Tulsa, Oklahoma 74116  
866-437-5863 | [Spectrumpaint.com](http://Spectrumpaint.com)