



Spec-Pro 3000 Flat (3101, 3102)

Spec-Pro 3000 Flat: An ideal flat coating formulated to provide perfect touch-up and final finishing for all interior new construction wall surfaces. Designed to feather smoothly after spray and back-roll of your final finish coat, using a fine nap roller to provide invisible touch-ups.

Recommended Substrates: Drywall, Wood, Masonry, Block, Plaster, Metal, Cement, Stucco.

Application: Stir product thoroughly with a circular, lifting motion ensuring even mixing throughout. Roller: 3/8" nap, depending on surface texture. Brush: Nylon or polyester filament. Airless Spray: Tip size and atomization pressure will vary with type of equipment, viscosity and temperature. Normally a tip size of .017 @ 2000-2500 psi will provide the most satisfactory spray pattern. Product may be thinned up to 10% with clean water for spray application if necessary. Best results are more likely obtained by using quality tools. Do not apply directly over chalky surfaces or bleeding stains. Apply when temperature is above 50 degrees Fahrenheit and in humidity less than 85%.

Product Type: Vinyl Acrylic
Volume Solids: 32.9 ± 1.0%
Weight Solids: 51.5 ± 1.0%
Weight Per Gallon: 11.6 lbs.
Viscosity: 108 - 113 KU (Krebs Units)
Flash Point: 200°F. or greater (TT-P-141, Method 4293)
Sheen: Flat, 0.5 - 1.0 units @ 85 Degrees
Wet Film Thickness: 4.0 to 5.4 mils
Dry Film Thickness: 1.3 to 1.8 mils
VOC: max of 90 g/L (.75 lbs/gal)

Dry Time: to touch = 30 mins; recoat = 4 hours; full cure = 10 days.

Thinner: Clean water.

Clean Up: Warm, soapy water.

Disposal: Dispose of contaminated absorbent, container and unused contents in accordance with local, state and federal regulations. Do not pour down a drain or storm sewer.

The surface to be painted must be clean and free of dirt, chalk, mildew, wax, grease, rust or loose, flaking paint. Dirt and chalk should be removed by scrubbing with warm soapy water and thoroughly rinsed with clean water. Mildew must be removed by scrubbing with a solution of one part household bleach and three parts water. Rinse well with clean water and allow it to dry thoroughly before painting. Wax should be removed with a commercial wax stripper or by solvent cleaning. Grease should be cleaned by using an appropriate emulsifier. Rust must be removed by hand sanding or by conscientious power tool cleaning. Remove loose paint, feather sand rough edges, dull glossy surfaces by light sanding. Remove sanding dust before paint application. Any exposed substrate should be spot primed with Spec-Pro 3000 or other appropriate primer.

Warning: Use only with adequate ventilation. Ensure fresh air during application and drying. If you experience eye watering, headache or dizziness or if air monitoring demonstrates vapor/mist levels are above applicable limits, wear an appropriate, properly fitted respirator (NIOSH approved) during and after application. Follow respirator manufacturer's directions for respirator use. Contains Ethylene Glycol & Crystalline Silica. In case of eye contact, flush immediately with plenty of water for at least 15 minutes and get medical attention immediately; for skin, wash thoroughly with soap and water. If you experience difficulty in breathing, leave the area to obtain fresh air. If continued difficulty is experienced get medical attention immediately. If swallowed, get medical attention immediately.

If spilled, contain spilled material and remove with inert absorbent. Dispose of contaminated absorbent, container and unused contents in accordance with local, state and federal regulations.

Obtain and read the MSDS prior to using this product. **KEEP OUT OF REACH OF CHILDREN.**