



SPEC-ONE 7000 Interior Eggshell (7201-7204)

SPEC-ONE 7000 Eggshell: A latex eggshell that dries to a durable, smooth finish. It exhibits excellent dirt and stain resistance and washes like an enamel without harm to the finish. It applies easily, has excellent hiding power and dries quickly. Incorporating advanced acrylic resin technology, it is a perfect choice for residential or commercial projects.

Recommended Substrates: Drywall, Plaster, Wood, Metal, Masonry, Stucco.

Application: Stir product thoroughly with a circular, lifting motion ensuring even mixing throughout. SPEC-ONE 7000 may be applied by brush, roller or spray at up to 450 square feet per gallon. Surface texture and porosity will affect actual yield. For best brush application results use quality polyester or nylon/polyester filament brush. For roller application, use 3/8" to 1" nap cover, depending on surface. Thinning is not normally necessary for brush or roller application. For spray application it may be thinned up to 15%, if needed. Do not apply if surface or air temperatures are below 55 degrees Fahrenheit.

Product Type: Acrylic
Volume Solids: 36.4 ± 1.0%
Weight Solids: 52.8 ± 1.0%
Weight Per Gallon: 11.2 lbs.
Viscosity: 90 to 95 KU (Krebs Units)
Flash Point: 200°F. or greater (TT-P-141, Method 4293)
Specular Gloss: 20 to 25 units @ 85 Degrees
Wet Film Thickness: 3.6 to 4.6 mils
Dry Film Thickness: 1.3 to 1.7 mils
VOC: max of 150 g/L (1.25 lbs/gal)

Dry Time: to touch = 30 mins; recoat = 4 hours; full cure = 10 days.

Thinner: Clean water.

Clean Up: Warm, soapy water.

Disposal: Dispose of contaminated absorbent, container and unused contents in accordance with local, state and federal regulations. Do not pour down a drain or storm sewer.

The surface to be painted must be clean and free of dirt, chalk, mildew, wax, grease, rust or loose, flaking paint. Dirt and chalk should be removed by scrubbing with warm soapy water and thoroughly rinsed with clean water. Mildew must be removed by scrubbing with a solution of one part household bleach and three parts water. Rinse well with clean water and allow it to dry thoroughly before painting. Wax should be removed with a commercial wax stripper or by solvent cleaning. Grease should be cleaned by using an appropriate emulsifier. Rust must be removed by hand sanding or by conscientious power tool cleaning. Remove loose paint, feather sand rough edges, dull glossy surfaces by light sanding. Remove sanding dust before paint application. Any exposed substrate should be spot primed with an appropriate primer.

Warning: Use only with adequate ventilation. Ensure fresh air during application and drying. If you experience eye watering, headache or dizziness or if air monitoring demonstrates vapor/mist levels are above applicable limits, wear an appropriate, properly fitted respirator (NIOSH approved) during and after application. Follow respirator manufacturer's directions for respirator use. Contains Ethylene Glycol & Crystalline Silica.

In case of eye contact, flush immediately with plenty of water for at least 15 minutes and get medical attention immediately; for skin, wash thoroughly with soap and water. If you experience difficulty in breathing, leave the area to obtain fresh air. If continued difficulty is experienced get medical attention immediately. If swallowed, get medical attention immediately.

If spilled, contain spilled material and remove with inert absorbent. Dispose of contaminated absorbent, container and unused contents in accordance with local, state and federal regulations.

Obtain and read the MSDS prior to using this product. **KEEP OUT OF REACH OF CHILDREN.**